
## REPLACEMENT SHEET METHOD FOR REMOVING OXIDE FROM CRACKS IN TURBINE COMPONENTS LAWRENCE BERNARD KOOL, ET AL. SERIAL NO. 10/749,486 ATTORNEY DOCKET NO. 136983-1

Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002


1/3



Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002

2/3








FIG. 6